

This document describes software package upgrade for WV-X4171/X4571L/X4571LM/X4170.

1. Release version: 4.10
2. Release Note Reference Number: X4171_008

WV-X4171/X4571L/X4571LM/X4170 Release Note

VER (ActiveX VER) Release Date	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence	
	A	B	C	U				
1.30 (4.50.33) Feb., '18					First production.			
1.40 (4.50.33) Mar., '18	C				For WV-X4171, WV-X4571L and WV-X4571LM only			
					-	-	Supported Extension Software WV-SAE303(W).	
						-	-	Added "Wide dynamic range" function.
						-	-	Added "SD memory card password lock" function.
						Defocus may occur depending on temperature change during operation	After resetting the back focus adjusted manually (click "Reset" at "Focus" in Back focus setting.	
						Black moving object looked noisy.	-	Improved.
				x		Administrator password may be deleted.	-	Fixed.
					x	-	-	Improved picture quality by reducing noises of moving objects while "Intelligent Auto" = "ON".
1.50 (4.50.33) Jun., '18	C						Improved communication stability by notifying switch to turn ECO mode OFF if using with the switch in "ECO mode".	
							Changed factory default setting for Authentication method; Previous: "Digest or Basic" New: "Digest" For more details: security_upgrade_June2018.pdf	
					x	-	-	Changed password policy that it must include at least 3 types of characters among "upper case letters / lower case letters / numbers / symbols". For more details, click here. Note: Original passwords and authentication method of products on the system are kept unchanged even firmware and software have been updated. For more details: security_upgrade_June2018.pdf
					x	-	-	Added user authentication at host authentication.
					x	-	-	Became saving history of login failure into system log.

*: ONVIF is a trademark of Onvif, Inc.

WV-X4171/X4571L/X4571LM/X4170 Release Note

1. Release version: 4.10
2. Release Note Reference Number: X4171_008

VER (ActiveX VER) Release Date	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence		
	A	B	C	U					
1.50 (4.50.33) Jun., '18	C				x	-	-	Added types of the Panasonic Alarm Notification as follow; SD Memory Card Write error SD Memory Card Read error SD Memory Card File Delete error SD Memory Card File system error SD Memory Card Other error	
					x	-	-	Changed factory default setting for "Bandwidth control(bit rate)" Previous: Unlimited New: 51200kbps	
					x	-	-	Changed factory default setting of "Shaping of stream from "On" to "Off".	
				x		Unable to change the settings of cgi command "reg_mailaddr".	-	Fixed.	
				x		If an RTSP header contains two or more User-Agent headers. no HTTP400(Bad Request) error returned and ignore the second and subsequent User-Agentheaders.	-	Fixed.	
1.51 (4.50.33) Aug., '18	C			x		Solid black image may be displayed due to outputting video takes time.	During sequence operation with the network disk recorder.	Fixed.	
				x		SD memory backup recording did not stop.	By turning power on / off while SD memory backup recording during connecting with the network disk recorder.	Fixed.	
		Revised on Sept. 7, 2018				x	Camera may restart by both network disk recorder with "SD memory backup" enabled or and image management software (WV-ASM series) are in sequence mode simultaneously .	-	Fixed.
				x		Camera may restart by downloading the data that backed up onto SD memory card.	-	Fixed.	
						Recording may not resume at restarting camera.	In a case the communication state is unstable.	Fixed.	
				x		Recording may not stop at communication restoration.		Fixed.	
		Revised on Nov. 7, 2018				x	Frame rate and bit rate may drop.	By transmitting H.264/H.265/JPEG live images continuously over 1 year without being rebooted.	Fixed.
				x		May not be able to zoom in with multi-screen display by dragging with mouse.	-	Fixed.	
		x		Camera may restart by disconnecting the camera's LAN cable while transmitting video in UDP.	In AC power operation.	Fixed.			
		x		Recorders may not detect alarm notification even if cameras detect VMD at Stream 2.	-	Fixed.			
		x		VMD on stream 2 through 4 may not detect by defining VMD area from recorders under 4-stream mode.	-	Fixed.			

*: ONVIF is a trademark of Onvif, Inc.

WV-X4171/X4571L/X4571LM/X4170 Release Note

- 1. Release version: 4.10
- 2. Release Note Reference Number: X4171_008

VER (ActiveX VER) Release Date	Priority Rank Level				Priority Rank Level A: Recommend to apply (Major or serious update) B: When issue happened C: Maintenance timing U: Function /Performance improvement (Not Necessary to update)	Contents		
	A	B	C	U		Issue (Phenomenon)	Occurrence condition	Correspondence
1.52 (4.50.33) Nov., '18				x		Multicast related settings ("Transmission type" setting and some others) may restore to the factory default settings by upgrading firmware from version 1.40 (or earlier) to version 1.50 (or later).	-	Fixed.
Ver1.61 (4.50.31) Dec., '18	C				x	-	-	Settings of "HTTP max segment size(MSS)" to be relating to the camera action; - JPEG transmission for Face Best Shot - "HTTP alarm notification"
				x		Camera may restart, unexpectedly. (Occurrence frequency: Rare)	In case of high load such as multi-stream transmission at 60fps etc.	Fixed.
				x		Camera may send corrupt AAC-LC data.	By receiving ONVIF command continuously.	Fixed.
				x		Camera may send corrupt AAC-LC data.	When the transmission is delayed due to the network environment etc.	Fixed.
				x		Video distribution may not be possible.	When the configuration of UI setting for Baseline Profile were as follow; - 30fps, H.264, FHD, Other than VBR	Fixed.
Ver4.00 (4.50.35) Feb., '19	C			x		The refresh interval value may not be reflected in the CGI command as follow; /cgi-bin/set_h264?f_priority=4&nr_framerate=1&h264_bandwidth=64&h264_quality=9&h264_ivop=0.2	-	Fixed.
				x		Black screen may be displayed back while recording H.264/H.265 to SD memory card and turning power Off and On.	-	Fixed.
					x	-	-	Improved resolution feeling in JPEG still image update at multi screen in full screen display.
				x		May not be able to change the save destination at the time of FTP periodical transmission error.	-	Fixed.
				x		ONVIF RTSP Multicast transmission may not work.	-	Fixed.
					x	-	-	Added dedicated URL for H.265 at RTSP; rtsp://<IP address>/Src/MediaInput/h265/stream_1
				x		The settings of SMTP server may return before the setting by restarting the camera.	-	Fixed.
				x		-	-	Enhanced security.
			x	-	-	Changed the URLs of hype-link destination according to change of support page URL (from "http" to "https").		

*: ONVIF is a trademark of Onvif, Inc.

WV-X4171/X4571L/X4571LM/X4170 Release Note

1. Release version: 4.10
2. Release Note Reference Number: X4171_008

VER (ActiveX VER) Release Date	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence
	A	B	C	U			
Ver4.00 (4.50.35) Feb.,'19	C			x	Displayed full screen on the main monitor when placing IE on the sub monitor and clicking the full screen display button.	When using the two monitor screens of main and sub.	Fixed.
				x	-	-	Improved the visibility of characters in the date/time screen.
				x	-	-	Improved the resolution feeling.
				x	-	-	Added a message as follow in the "Schedule" page; "VMD permission" is required when assigning the period to be detected. Setting is not necessary when detection at any time.
				x	-	-	Changed a message by clicking the Delete button in the log list window to; Delete the log and image as the result of retrieval including the page where log is not displayed. (All of data selected by "Event" and "Recording time" are deleted.)
				x	-	-	Fixed.
				x	-	-	Fixed.
				x	-	-	Fixed.
				x	-	-	Fixed.
				x	-	-	Improved the action of "/cgi-bin/get_io2?format=3&". [Note] Corrected not to notify by the above CGI response each time command alarm was continuously detected.
				x	-	-	Fixed.
				x	-	-	Fixed.
				x	-	-	Fixed.

*: ONVIF is a trademark of Onvif, Inc.

WV-X4171/X4571L/X4571LM/X4170 Release Note

1. Release version: 4.10
2. Release Note Reference Number: X4171_008

VER (ActiveX VER) Release Date	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence	
	A	B	C	U				
Ver4.00 (4.50.35) Feb.,'19	C			x	H.264 streaming of ch 4 may not be able to be delivered normally depending on the distribution order.	When multicast is delivered in 4 stream mode	Fixed.	
					-	-	-	Added switching function (automatic switching) of differential mode in order to increase the person counting accuracy at the time of local congestion
				x	Transmission type (H.264/H.265) and image capture size of stream may not be changed (transmission type and image capture size hold before change).	If those were changed within 2 minutes after the network had been disconnected with over RTSP connection.	Fixed.	
					-	-	-	Improved visibility of "SDREC" button on the window for tablet PC.
				x	-	-	-	Changed encryption method of setting data along with strengthening security. [Important Information] It is not possible to restore the setting data backed up with firmware version 4.00 (or later) to the camera that operates in version earlier than Ver 4.00.
Ver4.10 (4.50.35) June,'19	C			x	-	-	Security has been enhanced.	
				x	Audio may not output by attempting to connect two sessions simultaneously and failure to authenticate one of them.	-	Fixed.	
				x	-	-	Added a note in the window of DDNS setting page when using "Dynamic DNS Update", "Dynamic DNS Update(DHCP)".	
				x	-	-	Supported multi-browsers other than the Internet Explorer. Some restrictions apply: click here for details.	
				x	-	-	Improved smooth text display by changing the texts on the screen from 2 gradations to grayscale.	
				x	-	-	Added a CGI command to make an alarm; /Set?Func=SoftTrigger or /cgi-bin/Set?Func=SoftTrigger or /cgi-bin/comalarm.cgi	
				x	For Chinese market models only	-	-	Changed factory default setting of the time zone to Chinese Standard Time(CST), UTC+8.
				x	-	-	Added interference detection information to additional information when using the i-VMD function of Extension software.	
				x	-	-	Display the license of open source software (OSS) on upgrade screen.	
				x	ONVIF communication may become a cause of destroying resources.	-	Fixed.	
		x	-	-	Fixed Session Description Protocol/SDP (IPv6) on ONVIF.			

*: ONVIF is a trademark of Onvif, Inc.

WV-X4171/X4571L/X4571LM/X4170 Release Note

1. Release version: 4.10
2. Release Note Reference Number: X4171_008

VER (ActiveX VER) Release Date	Priority Rank Level				Issue (Phenomenon)	Occurrence condition	Correspondence
	A	B	C	U			
Ver4.10 (4.50.35) June,'19	C			x	Video may be black by changing the image capture mode to 25 fps with CGI (/ cgi-bin / setdata? IMG_MODE = 9m_25) because the frame rate settings for streams (1) and (2) are not 25 fps compliant.	-	Fixed.
				x	Unable to find ONVIF search.	-	Fixed.
				x	JPEG frame rate setting display becomes 0.33 fps by changing image capture mode rom 25 fps to 30 fps with CGI (/ cgi-bin / setdata? IMG_MODE) although actual transmission rate is 5 fps.	-	Fixed.
					-	-	The file may not be found by opening the log list during overwrite recording of the SD memory card and attempt to browse.
					-	-	The camera may restart by encrypting the stream 1 only, selecting audio transmission mode AAC-LC and recording video and audio simultaneously.
					-	-	Session registration may remain and video may not appear by changing Transmission type from "Unicast (Auto)" to "Unicast (Manual)".

Priority Rank Level
A: Recommend to apply (Major or serious update)
B: When issue happened
C: Maintenance timing
U: Function /Performance improvement (Not Necessary to update)

Contents

*: ONVIF is a trademark of Onvif, Inc.